


Foret à 60°-120° pour centrer. Forme B.




■ Acier rapide

#### Machines



#### Applications



#### Caractéristiques



#### Propriétés et bénéfices

+ Acier rapide : Substrat HSS ➡ Pour les usages généraux dans l'acier jusqu'à 950 N/mm², les fontes et les aluminiums.



| Code          | EAN           | Ø    | d2   | L  | I   | I.u | QTY | PCB |
|---------------|---------------|------|------|----|-----|-----|-----|-----|
| 8140821100040 | 3221910756109 | 1    | 4    | 25 | 0.8 |     | 1   | 1   |
| 8140821125050 | 3221910756130 | 1.25 | 5    | 25 | 1.1 |     | 1   | 1   |
| 8140821100060 | 3221910756116 | 1    | 6    | 25 | 0.9 |     | 1   | 1   |
| 8140821160063 | 3221910756161 | 1.6  | 6.3  | 35 | 1.3 |     | 1   | 1   |
| 8140821150080 | 3221910756147 | 1.5  | 8    | 31 | 1.3 |     | 1   | 1   |
| 8140821200080 | 3221910756178 | 2    | 8    | 31 | 1.6 |     | 1   | 1   |
| 8140821200100 | 3221910756185 | 2    | 10   | 40 | 2   |     | 1   | 1   |
| 8140821250100 | 3221910756192 | 2.5  | 10   | 35 | 2   |     | 1   | 1   |
| 8140821315112 | 3221910756239 | 3.15 | 11.2 | 45 | 3.1 |     | 1   | 1   |
| 8140821250120 | 3221910756208 | 2.5  | 12   | 40 | 2.5 |     | 1   | 1   |
| 8140821300140 | 3221910756222 | 3    | 14   | 45 | 2.5 |     | 1   | 1   |
| 8140821400140 | 3221910756246 | 4    | 14   | 50 | 3.1 |     | 1   | 1   |
| 8140821400180 | 3221910756253 | 4    | 18   | 50 | 3.9 |     | 1   | 1   |
| 8140821500180 | 3221910756260 | 5    | 18   | 55 | 3.9 |     | 1   | 1   |
| 8140821630200 | 3221910756284 | 6.3  | 20   | 50 | 3.9 |     | 1   | 1   |