

11111070002 | Broken Screw Extractor Kit M4 to M18 + N°2 Left-Turn Extractor M4 to M12 - 5 HCS Extractor + 1 X-Out Ø2 to 8 mm + N°2 Zamak Tap Holder M4-M12

COMPLETE KIT FOR BROKEN SCREWS AND TAPPING: Combined kit with 5 HCS spiral extractors, 1 X-Out Ø 2-8 mm and 1 zamac left-hand turner. For removing broken screws, studs or threaded rods from M4 to M18 and manually driving taps. Easy extraction of broken or damaged studs and screws. Durability thanks to HCS substrate and tool profile.

Set of M4 to M18 Broken Screw Extractors + N°2 M4 to M12 Left-Hand Turners - 5 HCS Extractors + 1 X-Out + N°2 M4-M12 Zamak Tap Holder



Machine



Données de gestion :

PCB : 1 / Kilogram. : 0,441 / Dimensions : 0300x0110x0055 mm / EAN : 3221912400413